

LAKE HAVASU CITY, ARIZONA

ADDENDUM NO. 2

Lake Havasu City Police Department Rehabilitation Project PROJECT NO. 103006

November 9, 2023

Attention is called to the following changes, additions, clarifications and/or deletions to the original solicitation and they shall be taken into account in preparing submissions:

There is no change in the opening date. **Submissions are due no later than 3:00 p.m., Arizona Time, November 21, 2023**, at the City Clerk's Office, 2330 McCulloch Blvd. N., Lake Havasu City, AZ 86403.

In accordance with the Information for Bidders, Section 00100 -16, Addenda and Interpretations, the following revisions to the Plans and Specifications shall become a part of the Contract Documents and each bidder shall acknowledge receipt thereof on page 00300-1 of the Bid Proposal.

- 1. Revised Plans (Not included herewith; please download separately)
- 2. Revised Project Manual (Not included herewith; please download separately)
- 3. Revised Plumbing Plans
- 4. Revised Bid Schedule- 00310 (Replace pages 00310-2 and 00310-3)
- 5. Revised Section Measurement and Payment- 01210 (Replace in its entirety)
- 6. Revised Crowther Engineering Memo- Structural
- 7. Questions & Answers
- 8. Plumbing Inspection Report

- 9. Pre-Bid Meeting Agenda & Sign-In Sheet
- 10. Plumbing As-Builts


BIDDER'S ACKLNOWELDGEMENT


DATE: _____

BY:	

Name: _____

Title: _____





COPPER, CONFORMING TO ASTM B-88. OR PEX CONFORMING TO ASTM F 876. PEX PIPING 1.5" AND LARGER MUST BE RIGID TUBING. <u>BELOW SLAB</u>: TYPE "K" SOFT DRAWN COPPER, CONFORMING TO ASTM B-88, WITH PLASTIC SLEEVE. PIPING, EXTERIOR BELOW GRADE ONLY:

PVC CONFORMING ASTM D 1785, WITH TRACER WIRE.



SHEET TITLE:


SHEET NO.

PLUMBING FLOOR PLAN

P1.01


1ST LEVEL

Note: Any changes made to final bid documents due to field changes will be billed hourly to the contractor.



KEYI	ED NOTES :	#	SEAL]
1. NOT US		FIXTURE(S) TO BE REPLACED	Kirk J.	
STOPS /	AND SUPPLY LINES.	ER, WASTE, AND VENT W/NEW ANGLE VARE TO BE REPLACED LIKE-FOR-LIKE	Hoffman / 5 No. 24488	
RECONN 4. PROVIDE	IECT ALL WATER. E NEW 4" DRYER DUCT ROUTED	D TO EXTERIOR OF BUILDING WITH WAL	EXPIRES 03/31/24	
	ID BACKDRAFT DAMPER. REFER E FLOOR DRAIN. SEE CONSTRU	·	DRAWINGS AND SPECIFICATIONS REMAIN THE PROPERTY OF THE DESIGN PROFESSIONAL. COPIES OF THE DRAWINGS AND SPECIFICATIONS RETAINED BY THE CLIENT MAY BE UTILIZED ONLY FOR HIS USE AND FOR OCCUPYING THE PROJECT FOR WHICH THEY WERE PREPARED, AND NOT FOR THE CONSTRUCTION OF ANY OTHER PROJECTS.	\$
	N IN JAIL AREA DISHWASHER U E EXISTING WALL CLEANOUT W	NIT. REPLACE CONNECTION. /NEW. VERIFY EXACT LOCATION IN FIEL	_D.	
8. REPLACE	E EDF W/NEW. SEE FIXTURE SO	CHEDULE FOR SPECIFICATIONS.		
			86403	
			HAE Y AZ	
			A N, L N	
			PROJECT NAME: LHC POLICE DEPARTMENT REI 2360 McCULLOCH BLVD. N, LAKE HAVASU CIT APN: 108-27-041A	
			ATA OCH	
			PROJECT NAME: LHC POLICE 2360 McCULLOCH APN: 108-27-041A	
			PROJECT NAME LHC F 2360 Mc APN: 106	
			SELBERG	
			ASSOCIATES	
			ARCHITECTURE &	
			2130 MESQUITE AVE. SUITE 204 LAKE HAVASU CITY ARIZONA 86403 (928) 855-6544	
<u>ruction note</u>)r drains & M	<u>.s</u> 10p sinks: rem	OVE EXISTING		
	P-TRAPS. REPL W/WATERLESS T			
) LINE W/EPOXY. E VENTING THRU	PROJECT NO.	_
VENTING THAT	HAS ALREADY	BEEN REPLACED	ISSUED FOR: PERMIT SE	
MAIN IN PLACE T IRON PIPE:			ISSUED DATE: SEPTEMBER 29, 202	3
	<u>reas</u> : replace Minimum one f	ALL ABOVE T ABOVE CEILING	REVISION ISSUE DATE	-
	PIPING TO EXIS	TING. OOR/SLAB UP TO	ADDENDUM	
CONNECT NEW	PIPING TO EXIS IT, REMOVE, AND	TING.		
D TO COMPLET	TE PLUMBING WC			
SLAB.				
FY EXACT LOC	ATIONS IN FIELD	AND COORDINATE.		
		Job #23PDL052 Tel: (480) 303-0180 Fax: (480) 302-7927	SHEET TITLE: PLUMBING FLOOR PLAN	
		8011 S Avenida del Yaqui Guadalupe, Arizona 85283	1ST LEVEL	-
		Note: Any changes made to final bid documents due to field changes will be billed hourly to the contractor.	SHEET NO.	┥

P1.02



 $\blacksquare \label{eq:linear}$

KEYED NOTES :

1. EXISTING MOP SINK TO BE REMOVED. CAP WASTE IN FLOOR, AND WATER AND VENT IN WALL.

(#)


- 2. ALL LABELED FIXTURES ARE EXISTING FIXTURE(S) TO BE REPLACED LIKE-FOR-LIKE. RECONNECT ALL WATER, WASTE, AND VENT W/NEW ANGLE STOPS AND SUPPLY LINES.
- 3. REPLACE EXISTING WALL CLEANOUT W/NEW. VERIFY EXACT LOCATION IN FIELD.
- 4. ABANDON WASTE BRANCH IN PLACE.

PLUMBING FIXTURE SCHEDULE

E SPECI	FICATIONS		FIXT	URE CO	ONNECT	IONS
rer Ber	FITTING & CAPACITY	ACCESSORIES/ REM <u>A</u> RKS	C.W.	H.W.	WASTE	VENT
EF" NQ	"SIOUX CHIEF" TRAP SEAL #835	– SQUARE TOP 3"– #832–35ANQ	-	-	2"	1½"
24	SERVICE FAUCET #830–AA	HOSE & BRACKET – MOP HANGER W/ VACUUM BREAKER	3⁄4 "	3⁄4 "	3"	2"
S .)	8 GPH OF 50°F WATER 115V, 1°	THREE PUSH PAD ACTIVATING 5 YEAR WARRANTY	1⁄2"	_	2"	1½"
$\overline{}$			$\overline{}$	$\overline{}$		$\overline{}$



N 2000	Kirk J. Hoffman o. 24488 11-06-2 CMA, U.S. ES O3/3	53. N N/24	PROPERTY
OF THE DESIGN PROFESS AND SPECIFICATIONS R UTILIZED ONLY FOR HIS PROJECT FOR WHICH T FOR THE CONSTRUCT	Sional. Cof Etained By Siuse and F Hey were	IES OF THE THE CLIEN OR OCCUP PREPARED	DRAWINGS IT MAY BE YING THE AND NOT
PROJECT NAME: LHC POLICE DEPARTMENT REHABILITATION	1 2360 McCULLOCH BLVD. N, LAKE HAVASU CITY, AZ 86403	APN: 108-27-041A	RECORD
SELBERG ASSOCIA	S TES		
ARCHITECTU PLANNING	RE &		
2130 MESQUITE A LAKE HAVASU CIT (928) 855-6544	/e. suite Y arizon	204 NA 86403	
PROJECT NO. ISSUED FOR: ISSUED DATE: REVISION		ISSU	23005 RMIT SET R 29, 2023 E DATE 1/03/23
SHEET TITLE:	1	6	
PL(JMBING		R PLAN LEVEL
SHEET NO.			
	Ρ	1.()3



P2.01

BID SCHEDULE LAKE HAVASU CITY

Lake Havasu Police Department Remodel 103006

ITEM <u>NO.</u>	DESCRIPTION	EST <u>QTY</u>	UNIT OF <u>MEASURE</u>	UNIT PRICE <u>(Word)</u>	UNIT PRICE ¹ (Figure)	ITEM TOTAL <u>COSTS²</u>
BASE E	BID					
1	Mobilization, Bonds, Insurance	1	L.S.		\$	\$
2	Division 2: Demolition work on Showers, Restrooms, and Flooring	1	L.S.		\$	\$
3	Division 4: Restoration of footing at exterior column and perimeter walls including waterproof coating				_ _ \$	\$
4	Division 8: Lobby Bullet Resistant Window and Jail Door Hardware replacement	215	C.Y.		_ _\$	\$
5	Division9: Jail Carpet, LVT Flooring, Wall Base, and Paint. Bathrooms Wall and Floor Tile, FRP Surfaces	2	EA		\$	\$
6	Division 12: Upper & Lower Cabinetry, and Countertops	1	L.S.		\$	\$

¹ The "Unit Price" column shall indicate unit or lump sum prices for each bid item and shall be indicated in written and numerical form. ² The "Item Total Costs" column shall indicate the extension of the unit prices, which is obtained by multiplying the "Estimated Quantity" column by the "Unit Price" column.

	BASE BID TOTAL ³ + FO	RCE AC	COUNT		_ \$	
9	Force Account:	1	L.S	Two Hundred Fifty Thousand Dollars	\$_250,000.00	\$_250,000.00
8	Public Safety Fueling Facility – Spezzano Way Southern Screen Wall	360	L.F.		_\$	\$\$
8	Division 26: Electrical work required to complete any of the mentioned work	1	L.S.		_\$	\$\$
7	Division 22: Plumbing Fixture Replacement, Sewer System Repair, Domestic Backflow Repair, and Related Concrete Demo & Repairs	1	L.S		\$	\$

³ The "Base Bid Total" amount shall be the sum of all costs listed in the "Item Total Costs". Additive Alternates are not to be included.

SECTION 01210

MEASUREMENT AND PAYMENT

PART 1 - GENERAL

1.1 Description

The outline of measurement and payment in this section is intended to provide a general guideline to the Contractor in preparing bids and submitting pay requests. Listing of work included in each bid item is not intended to include all work, but is to provide general guidance to the Contractor for allocating costs. All work will be paid for on a unit price basis with payment made for the quantity of each item completed.

All materials required for construction shall be furnished by the Contractor unless specifically stated. Items not specifically measured and paid for shall be considered as subsidiary items required to complete the installation in accordance with the intent of the contract documents. The Contractor shall include in the unit price bid items all costs associated with subsidiary items not being measured for payment.

1.2 Authority

Measurement methods delineated in the individual specification sections complement the criteria of this section. In the event of conflict, the requirements of the individual specification section govern.

Take all measurements and compute quantities. The Engineer will verify measurements and quantities.

1.3 Unit Quantities

Quantities indicated in the Bid Form are for bidding and contract purposes only. Quantities and measurements supplied or placed in the Work and verified by the Engineer shall determine payment.

If the actual Work requires more or fewer quantities than indicated, provide the required quantities at the unit prices contracted.

PART 2 – UNITS AND METHODS OF MEASUREMENT

2.1 General

All items that are included in the bid for measurement and payment are included herein. All other items of work shall be considered subsidiary to construction and will not be measured for payment.

2.2 Units and Methods of Measurement

2.2.1 Mobilization

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment and tools for all required bonds, insurance, mobilization of staff and equipment, and any other costs associated with complying with the contract administrative requirements and commencing work at the project site. This item also includes all work and materials necessary to complete the work as described in the plans and specifications. Payment for this item shall be lump sum and shall not be requested until at least thirty days from the notice to proceed has elapsed.

Payment for this item shall be made in accordance with Table A.

..

TA	ABLE A
Payment for Mobilization on First Partial Payment	Not to exceed 2.5% of the Lump Sum Base Bid
Subsequent payments for Mobilization	Not to exceed 2.5% of the Lump Sum Base Bid
Payment For Mobilization on Final Partial Payment	Any remaining Mobilization in excess of 5% of the Lump Sum Base Bid

2.2.2 Division 2: Demolition Work on Showers and Restrooms

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment, and tools for demolition, replacement and disposal of ceramic wall tile, floor tile, and wall carpet. Demolition work is described in plans and shall be replaced per the finish schedule on Sheet A2.03. Measurement and Payment for these items shall be per square foot.

2.2.3 Division 4: Restoration of footing at exterior column and perimeter walls

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing materials, labor and equipment, and tools for the restoration of footing at exterior column and perimeter walls including masonry waterproofing. Locations are specified in structural exhibit. There is no measurement for these items and Payment of these items shall be a lump sum.

2.2.4 Division 8: Lobby Bullet Resistant Window and Jail Hardware Replacement

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment, and tools for the replacement of the existing lobby communication window. The replacement includes the addition of a second transaction window that meets ADA requirements per plan specification. This includes the wall improvements necessary to accommodate this new window.

In addition, Contract Lump Sum Price for this item shall include the removal and replacement of the door hardware and sliding mechanisms at jail doors with AirTeq Sliding Mechanisms, software updates, and the rekeying of Jail doors. Measurement and Payment for these items shall be per unit.

2.2.5 Division 9: Jail Finishes: Carpet, LVT Flooring, Wall Base, Drywall Repair and Paint. Restroom Wall and Floor Tile, FRP Surfaces.

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment, and tools for installation of new finishes in Jail including carpet, LVT Flooring, wall base and paint as specified in plans per Sheet A2.03 Measurement and Payment for these items shall be per square foot.

2.2.6 Division 12: Upper and Lower Cabinetry

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment, and tools for removing, disposing, and installing new upper and lower cabinets and countertops as specified in plans. Measurement and Payment for these items shall be per linear foot.

2.2.7 Division 22: Plumbing Fixture Replacement and Sewer System Repair and Domestic Water Backflow Upgrade The Contract Lump Sum Price for this item shall constitute full

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment, and

tools for replacement of plumbing fixtures specified in plumbing plans and replace connection to dish washer unit. In addition, it shall include the repair of the sewer system which will include the following:

- The preparation and installation pit for the pipelining machine at three locations will require removal of the existing cleanout to allow alignment of the equipment with the pipe. New 2-way clean-out to be installed prior to backfill.
- Epoxy of underground cast iron sewer main lines, replace all "P" Traps, mop sinks, floor sinks and remove, and cap trap primers and installation of waterless trap seals.
- Administration Areas- Replacement of all cast iron pipes above floor slab up to minimum one foot above ceiling grid in first floor, connect new pipe to existing pipe.
- Jail Areas- Replacement of all cast iron pipes above floor slab up to the roof deck in Jail areas.
- Demolition and excavation work at Kitchen Grease Trap Area, replace failed cast iron two-way clean out.

Measurement and Payment for these items shall be per linear foot.

2.2.8 Division 26: Electrical Work

The Contract Lump Sum Price for this item shall constitute full compensation for furnishing all materials, labor, equipment, and tools for any electrical work that results of any of the above items and the addition of Bug-eye Emergency light at Trustee's Pod. There is no measurement for these items and Payment of these items shall be a lump sum.

END OF SECTION 01210



October 23, 2023

Selberg Associates, Inc. 2130 Mesquite Ave., Ste. 204 Lake Havasu City, AZ 86403

Subject: Police Department Remodel 2360 McCulloch Blvd N Lake Havasu City, AZ 86403 Crowther Engineering, LLC Project No. 23-402

To whom it may concern:

I am writing to provide my professional structural recommendations for the areas shown to me via photos by Brisa Barraza of Selberg Associates, Inc.

The structure listed above is constructed of Concrete Masonry Unit (CMU) blocks with concrete slabon-grade, and conventional spread footings and is estimated to have been constructed circa 1992. Figure 1 shows the locations highlighted in red on a plan view from the architect of the locations shown in the photos. Photos 1-3 show the deteriorated column, photos 4-6 show the wall, and photos 7-9 show other locations as shown from Figure 1.

It is our professional opinion that the current structural condition does not pose a life safety risk, and that the retrofits mentioned below should be performed in a timely manner such that further spalling and deterioration doesn't occur. Further deterioration may cause a life safety risk.

Masonry, if not constructed to be resistant to corrosive soils, may leach corrosive chemicals from the soils up from the ground and can cause deterioration of the masonry blocks. It is common to see the lower halves of walls deteriorate before the upper halves. Lack of grout may allow water intrusion inside the masonry cells and could potentially exacerbate the corrosion and deterioration of the masonry.

The structural retrofit for the columns from Photos 1-3 and 8 is shown in Figure 2 below. Where the exterior sidewalk is cracked in locations such as that in Photo 8, cut and remove the sidewalk square containing the cracked-off piece. Drill & epoxy #4x18" bars into the center of the existing concrete slab at 18-inches on center with Simpson Set-3G at new-to-existing slab locations.

Our recommendation for the wall spalls is to use a stiff wire brush to remove any loose debris and then apply a high-quality mortar such as Sikadur-35 Hi-Mod LV or equivalent to the spalls and cracks and ensuring the mortar penetrates the full depth of the CMU shell. A low-viscosity mortar may help to ensure there is adequate penetration into the CMU. The testing agency mentioned previously should apply a crack measuring system to determine if the spalls continue to grow over time after applying the mortar.

Our recommendation for the site wall shown in Figure 9 is to retrofit using the aforementioned mortar and wire brush, or per the structure owner option remove and replace may be desirable.



A breathable masonry sealant such as A-Tech Masonry & Brick Sealer or equivalent should be applied to at least the bottom two courses of masonry above grade (or from the top of the slab, whichever is greater) around the entire masonry structure and masonry columns to protect it from water intrusion. The sealant should be applied down to at least 6" below the bottom of the CMU (or 6" below grade, whichever is greater) onto the concrete stem. If ponding around the structure next to the walls has been an issue in the past then the architect should work with a civil engineer to mitigate ponding and ensure proper drainage away from the structure.

I believe this addresses the items that were brought to my attention. Please do not hesitate to contact me with any additional questions or concerns. Thank you!

Sincerely,



Layton B. Asmus, P.E. layton@croweng.com (928) 708-1665 ext. 108






Figure 1: Overall floor plan view





Photo 1: Front Face Exterior Deteriorated Column



Photo 2: Rear faces of exterior deteriorated column

1173 SOUTH 250 WEST, STE 304 St. George, UT 84770 (928) 708-1665





Photo 3: Close-up of exterior deteriorated column




Photo 4: Masonry spalls at wall

1173 SOUTH 250 WEST, STE 304 ST. GEORGE, UT 84770 (928) 708-1665





Photo 5: Typical masonry wall spalling







Photo 7: Close-up of masonry wall spalling & foundation deterioration



Photo 8: Close-up of column cracking





Photo 9: Site wall foundation deterioration






Figure 2: Column Retrofit Structural Requirements

Lake Havasu Police Department Remodel

Project # 103006

Pre-Bid Meeting Questions- 11/6/2023 - 10 am

Questions as noted:

1. Will contractor's employees be subject to background checks and/or daily

security checks?

Answer: 1. Any person working on site will have to pass the LHCPD Vendor Background

Check. 2. Daily security checks will be completed, only as needed. These screenings

will depend on the area of facility that is accessible to the employee.

2. Will there be new electric - one room calls for new lighting?

Answer: There is a new emergency light in the Trustee's dormitory

3. Will we have to set up dust walls?

Answer: Contractor must provide dust control. Type of dust control will vary,

depending on location within the facility.

4. Is there an asbestos & lead based paint report on the facility?

Answer: No, contractor to provide as needed.

5. Foundation of building and Courtyard/Outdoor Patio: Exposed foundation below

the CMU block, does this area need to be repaired?

Answer: Yes, the exposed slab/stem wall should be repaired and sealed, see Crowther

Engineering report. Dated 10/23/23

6. Plumbing chase between rooms; J-1, J-2, AI59, A161, AI63 – Are we replacing the cast iron vents within this chase.

Answer: No access available, leave cast iron plumbing vent in place.

7. Trustee's Dorm Shower ceiling; A153. Does the existing tile ceiling need to be impact resistant?

Answer: Existing tile ceiling; tile to be removed/floated/primed & painted, per spec.

8. Is Contractor responsible for new signage within jail/detention areas, specifically

signage on Sliding Detention door covers?

Answer: Yes, Contractor to provide Room Identifier # to each Detention door cover

after completion of painting.

9. What type of roof is on the existing building? Needed for patching of plumbing.

vent penetrations.

Answer: Existing roof plan calls "Hypalon Single Ply Roofing System (IRMA)". Our recommendation is to terminate the new PVC 12" below deck and connect it to existing cast iron. The penetration will be addressed in second phase when the roofing is done.

10. "Plumbing as-built" Please provide with Addendum 2.

Answer: Link Sent out with This Reply

11. Evidence bicycle canopy, will contractor need to relocate unit during plumbing

work?

Answer: No, LHCPD will relocate evidence and canopy during construction

12. Plumber's sewer line Inspection Report, will this be provided to bidders?

Answer: Yes, this report will be issued with Addendum 2.

13. How much sewer pipe is underneath the slab, total length of pipe requiring epoxy

restoration?

Answer: Refer to existing conditions plan to quantify the underground lines. (Link)

14. Report from Structural Engineer, will this be provided?

Answer: Yes, this will be provided with Addendum 2.

15. What type of plumbing clean outs are located just outside of the main lobby; they

are in paver walkway?

Answer: Roof drain/Stormwater; Not related to the sewer line restoration work.

16. Breakroom B103 Cabinetry; Replace with new to match new dispatch breakroom

B112?

Answer: Keep as is until phase 2

17. Admin and various areas outside of jail/detention unit; What type of drywall repair & painting is required on wall sections that are opened for plumbing work?

Answer: Repair drywall with texture to match existing surface. Prime and paint with

paint, color matched to existing finish.

18. Work hours allowed during construction project?

LHPD; to confirm and/or adjust answer.

Answer: Work hours will be Regular Daytime schedule. Consideration will be made on

an as needed basis if Contractor requests for night and weekend scheduling.

19. Detention Facility, sliding hardware mechanisms and locks, Who is providing?

Answer: Section 08 71 63 of Project Manual

Lake Havasu City Department of Public Works

Lake Havasu City Police Station

Sewer Line Inspection October 4th, 2023

Report Provided by

The following information documents our findings of the Camara, water jetting and inspection to investigate and determine the condition of the existing sewer that is below grade under the Lake Havasu Police Department Located at 2360 McCulloch Blvd N, Lake Havasu city, AZ 86403.

Location 1.

Starting at the rear of the building where the grease interceptor is located there is a 2-way cleanout leading into the building that has totally collapsed around the connection, causing rock, dirt, and debris to into the main line. This is causing the Kitchen to back up occasionally, this line enters the building and goes down the hallway also having smaller branch lines draining into it from the Jail cells, laundry room Kitchen continuing down the hallway and leads out the other side of the building where the entry gates are for evidence. Outside there are two clean outs in the dirt, this is where it exits into the city sewer system at the point of connection. Findings were a lot of Roughness in cast iron pipe, sections of the pipe are rotting at these locations. We are Recommend further Descaling, Jetting and Epoxy coating of the main line for easy flow conditions. Also Recommend a spot repair just outside the grease interceptor consisting of digging down make a spot repair and add two new cleanouts stopping the rock and debris from entering the system. Also recommend digging up all three locations where the sewer leaves the building, removing the existing clean outs to have better access for heavy cleaning and descaling the heavy build up in this line, then replacing with new cleanouts. Overall condition of pipe was found to be in fair but degrading conditions with light to heavy scaling.

Location 2.

Second location we went up stream from the exit point of where the kitchen comes out and found heavy scale and pipe rotting. Lines look to be all intact with a lot of build up and standing water in some spots mostly where the pipe rotting is that has caused buildup that has stuck to the walls of the pipe and the water is cutting through the grease and the grime which has created pipe rotting through the buildings system. Causing toilet paper, heavy debris to easily clog and get snagged by the narrow pathways. We recommend further Jetting and descaling this area to remove the heavy scale and build up to examine the side wall conditions to verify if there are and cracks or breaks hidden. After descaling you must protect the pipe from further rotting, we recommend Epoxy coating the entire underground system.

Location 3.

Our third location was inside the building. Removing a 4 inch clean out cap that was frozen and had to be cut out to gain access to the system just outside the Chiefs office that is receiving waist from above. We recommend replacing the cast iron piping from the floor up through the T-bar ceilings preventing future cracking that is occurring. Also, this section of piping below ground has very heavy scaling build up and has pipe rot due to this build up approx. 30 feet long. Recommending heavy descaling, jetting and Epoxy coating.

Location 4.

The fourth location was outside the evidence room in the outside cage. There are two clean outs going both ways we ran the jetting line up the line 80 feet finding a lot of soap scum and build up. The lines seem to be in good condition as far as being intact and there are no major holes or separations. They did have a little build up at a few fittings that was hard to get through due to the buildup. There are six tie-in locations on this line that get choked down due to the build up of cast iron debris and scaling. Recommend descaling and jetting and Epoxy coating. This would repair the issue properly.

Further Recommendations would be calculating the entire building to get a more accurate amount of footage needing to be epoxy coated throughout the entire building. We also would recommend locating any floor drains, floor sinks, or mop sinks throughout the building. These would need to be sawcut and removed to gain access and remove the P-Traps underground to access the lines properly for epoxy coating, and then replacing them with PVC after the process has been completed. This would include thoroughly cleaning and descaling the entire system. Then utilizing an epoxy coated system would reseal and smooth the inside of the pipe to be better than new condition. At this time said underground plumbing does not have to be replaced yet. But if left untreated the pipe may rapidly degenerate over the next 5 to 7 years. If treated with epoxy the pipe can be guaranteed for the next 25 years and potentially last much longer than that. At this time if all cast iron pipes were maintained and epoxy coated, we see no need to replace the current underground system.



Police Department Rehabilitation Project Pre-Bid Meeting Agenda November 6, 2023, 10:00 am 1.)Round table Introduction and Sign-In Sheet.

- 2.)Project Plans and Specifications are available on the City's website at www.lhcaz.gov or on DemandStar at www.demandstar.com.
- 3.) The scope of work includes, in general terms, the following:

This project consists of restoration of footings at an exterior column and perimeter walls, bullet resistant window installation and jail door hardware replacement, jail carpet, LVT flooring, wall base, paint, wall and floor tile replacement in bathrooms, upper and lower cabinet replacement, plumbing fixture replacement, sewer system repair and any electrical work required to complete any of the mentioned work.

- 4.) Preparation and Submission of Bids:
 - a. Found in section 00300.

5.)Contract Time:


- a. There are <u>150 Calendar days</u> allotted for the completion of the project.
- b. Questions due November 13, 2023
- c. Bid Opening Date: November 21, 2023
- d. Anticipated Award Date: December 12, 2023
- e. Anticipated Contract Signing Date: December 22, 2023
- f. Anticipated Issuing Notice to Proceed: January 8, 2024
- g. Anticipated Construction begin date: January 18, 2024
- 6.)General questions?





PROJECT NAME: Lake Havasu City Police Department Rehabilitation Project


PROJECT NO.: PN 103006


DATE: Monday November 6 2023











G	
29)	" CW DOWN IN WALL AND OUT TO BACKFLOW PREVENTOR.
30.	REDUCED PRESSURE BACKFLOW PREVENTOR: "WATTS" MODEL #900 REDUCED PRESSURE BACKFLOW PREVENTOR, 3/4" SIZE, RUN VENT DRAIN LINE TO NEAREST FLOOR SINK, AND INSTALL AT A +48" A.F.F. OF EQUIPMENT YARD.
31)	4" WASTE DOWN, 2" VENT UP WITH WCO, AND 2" VENT OVER ABOVE CEILING AS SHOWN.
(32)	2" VTR.
33)	3" WASTE DOWN, 1-1/2" VENT UP WITH WCO, AND 1-1/2" VENT OVER ABOVE CEILING AS SHOWN.
(34.)	MECHANICAL EXPANSION TANK: SEE MECHANICAL DRAWINGS.
35.)	4" FLOOR SINK, INSTALL IN CONCRETE PAD SET AT +2" ABOVE FINISHED FLOOR OF EQUIPMENT YARD.
(36.)	3." FLOOR SINK, INSTALL IN CONCRETE PAD SET AT +2" ABOVE FINISHED FLOOR OF EQUIPMENT YARD.
(37)	CHEMICAL TREATMENT: SEE MECHANICAL DRAWINGS.
(38.)	(2) 2" VENTS UP FROM BELOW GRADE TO +12" ABOVE TOP OF WALL WITH #23 OPW VENT CAPS.
(39)	2" VENT LINES EXTENDED OVER BELOW GRADE.
40.	INDICATES TERTIARY LINER.
(41)	LEAK DETECTION CABLE IN CONDUIT.
42.)	4" DIAMETER PERFORATED FIBERGLASS PIPE WITH 1/4" HOLES ON BOTTOM 180° FOR LEAK DETECTION.
43.)	SLOPE LINER TOWARDS PERFORATED PIPE (TYPICAL).
44.)	2" DOUBLE CONTAINMENT FUEL SUPPLY LINE OVER BELOW GRADE
(45.)	FUEL DISPENSER: SEE SPECIFICATIONS.
46.	2" FUEL SUPPLY LINE UP FROM BELOW GRADE TO FUEL DISPENSER.
47,	EMERGENCY GENERATOR: SEE ELECTRICAL DRAWINGS FOR EXACT LOCATION.

- (48) · 3/4" DIESEL OIL SUPPLY LINE UP FROM BELOW SLAB TO EMERGENCY GENERATOR WITH S.O.V.
- (9) 3/4" FOG # 1" FOR LINES TO & FROM GENERATOR DAY TANK VERIFY EXACT LOCATION IN FIELD
- (50) F.O.S. & F.O.R. LINES BELOW GRADE

 \bigcirc

KEYED NOTES (SUPPORT BUILDING)


- (1)1-1/2" CW BUILDING S.O.V. AT +12" ABOVE FINISHED FLOOR. 3/4" CW H.B. IN RECESSED BOX WITH LOCKABLE DOOR.
- (2.) 4" AREA DRAIN WITH SEDIMENT BUCKET.
- (4.) HOSE REEL: SPEALFIED IN OTHER SECTION OF SPECIFICATIONS, ROUGHIH 12"OW & AIR VERIFY EXACT LOCATION WITH ARCHITECT, PLUMBING CONTRACTOR TO FURNISH & INSTALL.
- (5.)INDUSTRIAL WASTE INTERCEPTOR: "SMITH PRECAST" MODEL 750 GALLON INTERCEPTOR WITH TRAFFIC RING AND COVER SET 1" ABOVE FINISHED GRADE. RING & COVER TO BE HEAVY DUTY TYPE
- 6.) 2" VENT LINE UP OFF TOP OF LINE AT 45°L OVER BELOW GRADE AS .SHOWN .

(7.)4" SCO.

- (8.) SEE CIVIL DRAWINGS FOR CONTINUATION OF 4" WASTE, 1-1/2" CW & I" MEDIUM PRESSURE GAS MAIN
- ٩. 2" VENT LINE UP IN WALL FROM BELOW SLAB TO ABOVE CEILING & OVER AS SHOWN.
- (10.) 2" VENT THROUGH ROOF.
- (11) 1/2" AIR LINE DOWN IN WALL TO BELOW GRADE & OVER TO HOSE REEL .
- (12) 12,000 GALLON UNDERGROUND FUEL STORAGE TANK: SEE SPECIFICATION THIS SHEET.
- (13) 2.500 GALLON UNDERGROUND DIESEL FUEL STORAGE TANK: SEE SPECIFICATIONS THIS SHEET.
- (14) 3/4" CW DOWN IN WALL AND OUT TO 3/4" CW H.B. AT +18" ABOVE FINISHED GRADE. TYPICAL WHERE SHOWN.
- (15.) 4" F.D. WITH SEDIMENT BUCKET.
- (16.) OIL INTERCEPTOR: "J.R. SMITH" MODEL SPGT-350 INTERCEPTOR, PROVIDE TRAFFIC RING AND COVER AT +2" ABOVE FINISHED GRADE. PROVIDE RISER RINGS IF NECESSARY.
- (17.) 4" SCO WITH 2" VENT LINE EXTENDED OVER BELOW GRADE UP IN WALL TO BELOW ROOF, RUN VENT LINE AS HIGH AS POSSIBLE.
- AIR COMPRESSOR: "CHAMPION" MODEL R-10C, UNIT MODEL (18) HRI-3, 30 GALLON TANK CAP, 1-1/2" H.P., 542 RPM, 480V 3PH, 10.5 CFM FREE AIR AT 125 PSI. INSTALL ON FLOOR.
- (19) 1/2" AIR LINE UP IN WALL TO BELOW ROOF, RUN AS HIGH AS POSSIBLE.
- 20. 1" CW DOWN IN WALL TO P-1.


- SEE DETAIL $\begin{pmatrix} C \\ P.3 \end{pmatrix}$


- 21. 4" WASTE DOWN 4" VENT UP WITH WCO 4" VTR. 22. 1/2" CW DOWN IN WALL, 1/2" CW TO P-5, 1/2" CW TO POINT OF
- USE WATER HEATER, 1/2" HW FROM POINT OF USE WATER HEATER TO P-5. 23. POINT OF USE WATER HEATER: "ITS" MODEL MDT-6000-208,
- 6KW, 277V, 3PH, .8 GPM AT 50° RISE.
- 24. 2" WASTE DOWN 1-1/2" VENT OVER IN WALL.
- (25) 1/2" AIR LINE DOWN NEXT TO WALL TO QUICK DISCONNECT AT +6" ABOVE COUNTER TOP. (26.) 1/2" CW DOWN IN WALL, 1/2" CW TO P-8 , 1/2" CW TO POINT
- OF USE WATER HEATER, 1/2" HW FROM POINT OF USE WATER HEATER TO P-8 . (27.) 2" WASTE DOWN - 1-1/2" VENT UP, OVER ABOVE CEILING TO
- VENT RISER AT FIXTURE P-1.
- 28. 1/2" AIR LINE OVER ALONG WALL AT +36" ABOVE FINISHED - FLOOR.





WALL AT 24 ABV. FIL. PLOOR (9)

KRACKOF











(37)

1215

(1()



ROBERTS/DINSMORE ASSOCIATES


ONE GATEWAY 426 NORTH 44th STREET SUITE 100 PHOENIX, ARIZONA 85008 TELEPHONE (602)275-6830 CONSULTANTS


Norman Engineering Group 7330 North 16th Street Suite 0201 Phoenix, Arizona 85020 (602) 371-0397

STRUCTURAL Alagia Engineering Group 1010 East Missouri Avenue Phoenix, Arizona 85014 (602) 264-1010 MECHANICAL, ELECTRICAL & PLUMBING

Tesco 2122 West Indian School Road Phoenix, Arizona 85015 (602) 264-3070 KITCHEN CONSULTANT

Dave Keaggy & Assoc. 2935 East Clarendon Avenue Phoenix, Arizona 85016 (602) 224-5571







DATE - 12/18/91 ISSUED FOR DATE A COMMENTS 4-3-92 SHEET TITLE PLUMBING FLOOP PLAN SUPPORT BUILDING DETAILS


TESCO, Inc SHEET NO. **P-3** R/DA PROJECT NO.


91006



WATER HEATER SCHEDULE								
RAGĘ		C.F.H,	REC. AT	VENT	PIP			REMARKS
P. GAL.	GAS	INPUT	100 [°] F T. R.	SIZE	CW	нพ	GAS	
250	HAT.	270	226	7 ¹¹	2"	2 ¹¹	11/4"	
25	HAT	199	167	6"	2"	2"	11	









PLUMBING SYMBOL LIST						
SYMBOL		SYMBOL	The second se			
Contraction of the second second	SOIL WASTE LINE (W)		SHUT OFF VALVE (GATE)			
	VENT LINE (V)		CHECK VALVE			
	COLD WATER (C.W.)	——	UNION			
	HOT WATER (H.W.)		LUBRICATED PLUG VALVE			
	HOT WATER RETURN		HOSE BIBB (H.B.)			
<u> </u>	GAS LINE		BRANCH RISE OFF MAIN			
<u></u> TW;	TEMPERED WATER	ØS.C.O.	SURFACE CLEANOUT			
D`	DRAIN LINE	ØF.C.O.				
	BUILDING SEWER		GLOBE VALVE			
0	FLOOR DRAIN (F.D.)	δι	BALL VALVE			
	FLOOR SINK (F.S.)		ROOF DRAIN LEADER			
0	ROOF DRAIN (R.D.)	<u> </u>	OVERFLOW DRAIN LEADER			
0	OVERFLOW DRAIN		CONDENSATE DRAIN LINE			
			INDUSTRIAL COLD WATER			

MARK	LUMBING FIXTU	W,	V.	C.W.	H.W,	
P-1	WATER OLOGET	41	2'	11	 	FL. VALVE, WALL HUNG
PIA	WATER CLOSET	4"	21	¹⁰		FL. VALVE HANDIGAPPED
P.2	WATER CLOSET	41	21	11		FL. VALVE FLR MOULTE
P3	WATER CLOSET/LAV.	4"22"	2"	"E 2"	1/2"	FL. VALVE WALL HUNG
PBA	WATER CLOSET/LAV.	4'\$2"	2"	1 # 1/2"	1/2"	FL. VALVE WALL HUNG
P-4	URINAL .	21	11/2"	3/411		FL. VALVE WALL HUNG
P5	LAVATORY	21	1/2"	1/2"	$1/2^{1}$	WALL HUNG
F5A	LAVATORY	211	1/2	1/2"	$1/2^{11}$	WALL HUNG - HANDIC.
P-6	LANATORY	21	1/2	1/2"	1/21	COUNTERTOP RAIND
P-7	blower.	2"0R3"	11/21	1/2"	1/21	FIELD EUILT
P-7A	shower	2	1/2"	1/2"	1/2"	FIELD BUILT
P8	SINK	21	1/2"	1/2"	$ 2^{11}$	STAILESS STEEL
<u>P9</u>	SILK	2	1/2	1/21	1/21	STANLESS STEEL
P-9A	SINK . 2. COMPMY	2"	1/2	1/2"	1211	STAINLESS STEEL
FIO	ELECT, DRINK, FOUNTAIN	2"	1/2	1/21		OBMI · RECESSED
PII	ELECT. DRIHK, FOUL TAIN	2"	11/21	1/2"		WALL HUNG - HANDIC.
E12	SERVICE SILK	3"	! / 2	1/21	1/2"	FLOOR MOUNTED
P13	WATER CLOSET	41	21		~~~	FL.VALVE FLR HTD
F-14	URIHAL	21	1/21	3/411		FL. VALVE , WALL HUNG
PIS	LAVATORY	2"	1/21	1/2"	1/211	COUNTERTOP HANDIC,
F16	WATER CLOSET	4"	211	li I		FURNISH COMPLETE .
-P-17	LOVATORY	2"	11/2"	1/211	121	FURHISH COMPLETER

