To Whom It May Concern:

I hereby attest that Josh Sondrol is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

_____
Signature

STATE OF ARIZONA   )
   ) ss
COUNTY OF MOHAVE   )

Subscribed and sworn to before me this ____28____ day of ___March___.

___2016___ by ___Josh Sondrol_____

___Carla Duarte_____
NOTARY PUBLIC

___3/28/16_____
DATE

Commission expires:

CARLA DUARTE
Notary Public - Arizona
Mohave County
My Comm. Expires Mar 29, 2017

Area Code 928

Administration 855-4884	Fax #'s	Emergency 9-1-1
Business Office 855-1171	Administration 680-5430	Non-Emergency Dispatch/ 855-4111
Investigations 855-5775	Business Office 680-5431	TDD 855-4114
Patrol 855-0515	Investigations/Patrol 680-5432	Havasu Silent Witness 854-TIPS

E-mail: police@lhcaz.gov

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST J Sandral 187   AGENCY LHC PD

DATE 3/22/16   TIME 2355

INTOXILYZER SERIAL # 80-003355   LOCATION MAIN JAIL

(✓) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution . 100 AC.

                                OR

       Pour a standard alcohol concentration solution _____ AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C

(✓) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"

(✓) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.

(✓) 4. Air blank completed.

(✓) 5. Calibration check completed. Test results 0. 100 AC.

(✓) 6. Air blank completed.

(✓) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE Q Sandral 187

DPS Form Exh G-2 (Rev 05-01)

INTOXILYZER 8000
Location: MAIN JAIL
Serial Number: 80-003355
Core Version: 8105.48
03/22/2016   23:55:32

Standard Lot#: 20314100A3
Last Changed By: J. SONDROL #187

QAS: J. SONDROL #187
LAKE HAVASU CITY PD

Operator: J. SONDROL #187
LAKE HAVASU CITY PD

Test   g/210L   Time

Air Blank   0.000   23:56:12
0.100 Cal Check   0.100   23:56:33
Air Blank   0.000   23:57:02

        Preventative Maintenance
        Performed -- Timer Reset

EXHIBIT G-4
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST __J Sandrok 187__ AGENCY __LHC PD__

DATE __3/23/16__ TIME __0003__

INTOXILYZER SERIAL # __80-003355__ LOCATION __Main Jail__

(✓) 1. Display Reads "PUSH BUTTON TO START"

DIAGNOSTIC TESTS
(✓) 1. Clock time check.
(✓) 2. Date check.

OPERATIONAL TESTS
(✓) 1. Alcohol-free subject test result 0. __000__ AC.
(✓) 2. Error recognition logic system functioning.
          Not a Successfully Completed Test Sequence printed
(✓) 3. Proper sample recognition system.
          Not a Successfully Completed Test Sequence printed
          Deficient sample printed.
(✓) 4. Standard Calibration Check standard 0. __100__ AC. Result 0. __100__ AC.

Instrument is operating properly and accurately.   YES __✓__ NO _____

COMMENTS

_____

_____

_____

_____

SIGNATURE __Q Sandk 187__

DPS Form Exh G-4 (Rev 05-01)

```
INTOXILYZER 8000
Location: MAIN JAIL
Serial Number: 80-003355
Core Version: 8105.48
03/23/2016                        00:03:50

Standard Lot#: 20314100A3
Last Changed By: J. SONDROL          #187

QAS: J. SONDROL                      #187
LAKE HAVASU CITY PD

Operator: J. SONDROL                 #187
LAKE HAVASU CITY PD

Subject: SQAP,TEST
DOB: 01/01/1950
Sex: M              Weight: 123

15 Minute Deprivation Period? Yes


Test                g/210L        Time
Air Blank           0.000          00:04:39
Diagnostic Test     Pass           00:05:14
Air Blank           0.000          00:05:41
0.100 Cal Check     0.100          00:06:02
Air Blank           0.000          00:06:31
Subject Test        0.000          00:06:49
Air Blank           ABT*           00:06:56
Air Blank           IPS**          00:07:03

*Sequence Aborted
**Improper Sample
```

Not a Successfully Completed Test Sequence

```
INTOXILYZER 8000
Location: MAIN JAIL
Serial Number: 80-003355
Core Version: 8105.48
03/23/2016                          00:07:45
```

Standard Lot#: 20314100A3
Last Changed By: J. SONDROL   #187

QAS: J. SONDROL   #187
LAKE HAVASU CITY PD

Operator: J. SONDROL   #187
LAKE HAVASU CITY PD

Subject: SQAP,TEST
DOB: 01/01/1950
Sex: M   Weight: 123

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	00:08:30
Diagnostic Test	Pass	00:09:05
Air Blank	0.000	00:09:33
0.100 Cal Check	0.100	00:09:53
Air Blank	0.000	00:10:23
Subject Test	0.203*	00:13:30
Air Blank	0.000	00:14:03
Air Blank	0.000	00:14:31
Subject Test	XXX**	00:14:55
Air Blank	RFI***	00:15:03

*Deficient Sample
**Invalid Sample
    Begin new deprivation period
***RFI Detect

Not a Successfully Completed Test Sequence

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST J Sandral 187   AGENCY LNC PD

DATE 3/23/16   TIME 0016

INTOXILYZER SERIAL # 80-003355   LOCATION Main Jail

(✓) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution . 100 AC.

OR

Pour a standard alcohol concentration solution _____ AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C

(✓) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"

(✓) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.

(✓) 4. Air blank completed.

(✓) 5. Calibration check completed. Test results 0. 100 AC.

(✓) 6. Air blank completed.

(✓) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE C Sandral 187

DPS Form Exh G-2 (Rev 05-01)

```
INTOXILYZER 8000
Location: MAIN JAIL
Serial Number: 80-003355
Core Version: 8105.48
03/23/2016                        00:16:13
-------------------------------------------
Standard Lot#: 20314100A3
Last Changed By: J. SONDROL #187
-------------------------------------------
QAS: J. SONDROL #187
LAKE HAVASU CITY PD
-------------------------------------------
Operator: J. SONDROL #187
LAKE HAVASU CITY PD
-------------------------------------------


Test                 g/210L        Time
-------------------------------------------
Air Blank            0.000         00:16:42
0.100 Cal Check      0.100         00:17:03
Air Blank            0.000         00:17:33



        Preventative Maintenance
        Performed -- Timer Reset
```