



POLICE DEPARTMENT
LAKE HAVASU CITY
2360 McCULLOCH BOULEVARD NORTH
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

Michael Maloy Jr. # 281
Signature

STATE OF ARIZONA)
) ss
COUNTY OF MOHAVE)

Subscribed and sworn to before me this 14th day of July.

2023 by MICHAEL MALOY

Shawna McKnight
NOTARY PUBLIC

July 14, 2023
DATE



Commission expires:

May 4, 2025

Area Code 928

Administration 855-4884
Business Office 855-1171
Investigations 855-5775
Patrol 855-0515

Fax #'s
Administration 680-5430
Business Office 680-5431
Investigations/Patrol 680-5432

E-mail: police@lhcaz.gov

Emergency 9-1-1
Non-Emergency Dispatch/ 855-4111
Havasü Silent Witness 854-TIPS

EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALOY #281 AGENCY LHCPD
DATE 07-14-2023 TIME 06:48
INTOXILYZER SERIAL # 90-003679

☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

DIAGNOSTIC TESTS

- ☒ 1. Clock time check
☒ 2. Date check

OPERATIONAL TESTS

☒ 1. Deficient Subject Test (Proper Sample Recognition)

Deficient Sample printed

☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):

0.000 AC

☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):

Invalid Sample – Begin new deprivation period printed

☒ 4. Radio Frequency Interference Test (Error Recognition):

RFI Detect printed

☒ 5. Standard Calibration Check:

0.101 AC

☒ 6. Air Blanks Completed

☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

STANDARD CHANGE

P.S.I. 1,000

SIGNATURE

Michael Maloy Jr #281

DPS Form Exh I-2 (Rev 19-03)

ARIZONA FORENSIC BREATH ALCOHOL
ANALYTICAL REPORT

INSTRUMENT INFORMATION

Analytical Instrument: INTOXILYZER 9000
Serial Number: 90-003679
Software Version: 9439.01.00
Analytical Report Number: 36790714230139
QAS: MALOY, MICHAEL
QAS Permit #: 30178
Agency: LAKE HAVASU PD
Last 31-Day Check: 05/19/2023
Last Annual Maintenance: 11/29/2022

SUBJECT INFORMATION

Test Date: 07/14/2023
Name: 31-Day Check,
Driver's License #:
Weight:
Gender:
State of Issue:
Date of Birth:
Driver's License Expiration:
Age:
Deprivation Start Time: 06:30
15-Minute Deprivation: Yes

OPERATOR INFORMATION

Name: MALOY, MICHAEL
Agency: LAKE HAVASU PD
Permit #: 30178

STANDARD INFORMATION

Standard Value: 0.100
Standard Lot #: 302-402690546
Expiration Date: 05/24/2025
Bottle #: 006
Last Changed By: MALOY, MICHAEL
Permit #: 30178

Test	g/210L	Time
Air Blank	0.000	06:48:49
Diagnostic Test	PASS	06:49:25
Air Blank	0.000	06:50:02
Calibration Chk	0.101	06:50:24
Air Blank	0.000	06:51:04
Subject Test 1	DEF*	06:54:17
Air Blank	0.000	06:55:00
Air Blank	0.000	06:55:40
Subject Test 2	0.000	06:57:15
Air Blank	0.000	06:57:56
Wait		07:01:59
Air Blank	0.000	07:02:37
Subject Test 3	INV**	07:03:18
Air Blank	RFI***	07:03:31

*Deficient Sample

**Invalid Sample - Begin new deprivation period

***RFI Detect

Not a Successfully Completed Test Sequence

RESULTS

EXCEPTION MESSAGES

* Deficient Sample

** Invalid Sample - Begin new deprivation period

*** RFI Detect

All air blank results must be 0.000.

Consecutive subject test results must not differ by more than 0.020 g/210L.

Standard check results must be ±10%.

Intoxilyzer - Alcohol Analyzer
Model 9000

SN: 90-003679
Test Date: 07/14/2023
Test Time: 06:45

Location:

Software Version: 9439.01.00

Standard Lot #: 302-402690546
Standard Value: 0.100
Expiration Date: 05/24/2025
Bottle #: 006
Last Changed By: MALOY, MICHAEL
Permit #: 30178

Operator: MALOY, MICHAEL
Permit #:30178
Agency: LAKE HAVASU PD

Test	g/210L	Time
Air Blank	0.000	06:46:17
Calibration Chk	0.102	06:46:39
Air Blank	0.000	06:47:19

No RFI Detected

Successfully Completed Test Sequence

STANDARD
CHANGE