




POLICE DEPARTMENT  
**LAKE HAVASU CITY**  
2360 McCULLOCH BOULEVARD NORTH  
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

  
Signature # 281

STATE OF ARIZONA )  
 ) ss  
COUNTY OF MOHAVE )

Subscribed and sworn to before me this 13 day of AUGUST.

2022 by MICHAEL MALOY  


NOTARY PUBLIC

8-13-2022

DATE

Commission expires: 3-16-2025



Area Code 928

Administration ..... 855-4884  
Business Office ..... 855-1171  
Investigations ..... 855-5775  
Patrol ..... 855-0515

Fax #'s  
Administration ..... 680-5430  
Business Office ..... 680-5431  
Investigations/Patrol ..... 680-5432

E-mail: [police@lncaz.gov](mailto:police@lncaz.gov)

Emergency ..... 9-1-1  
Non-Emergency Dispatch/ ..... 855-4111  
Havasu Silent Witness ..... 854-TIPS

281

EXHIBIT I-2  
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY  
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALDY #281 AGENCY LNCPO  
DATE 08-13-2022 TIME 1744  
INTOXILYZER SERIAL # 90-003695

1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

DIAGNOSTIC TESTS

1. Clock time check  
 2. Date check

OPERATIONAL TESTS

1. Deficient Subject Test (Proper Sample Recognition)  
Deficient Sample printed
2. Alcohol-free Subject Test (Proper Sample Recognition):  
0. 000 AC
3. Mouth Alcohol Subject Test (Proper Sample Recognition):  
Invalid Sample – Begin new deprivation period printed
4. Radio Frequency Interference Test (Error Recognition):  
RFI Detect printed
5. Standard Calibration Check:  
0. 099 AC
6. Air Blanks Completed  
 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES  NO

COMMENTS:

---

---

---

SIGNATURE Michael Maldy #281

ARIZONA FORENSIC BREATH ALCOHOL  
ANALYTICAL REPORT

INSTRUMENT INFORMATION  
Analytical Instrument: INTOXILYZER 9000  
Serial Number: 90-003695  
Software Version: 9439.01.00  
Analytical Report Number: 36950813220007  
QRS: MALLOY, MICHAEL  
QRS Permit #: 30178  
Agency: LAKE HAVASU PD  
Last 31-Day Check: 06/30/2022  
Last Annual Maintenance: 11/15/2021

SUBJECT INFORMATION  
Test Date: 08/13/2022  
Name: 31-Day Check,  
Driver's License #:  
Weight:  
Gender:  
State of Issue:  
Date of Birth:  
Driver's License Expiration:  
Age:  
Deprivation Start Time: 17:25  
15-Minute Deprivation: Yes

OPERATOR INFORMATION  
Name: MALLOY, MICHAEL  
Agency: LAKE HAVASU PD  
Permit #: 30178

STANDARD INFORMATION  
Standard Value: 0.100  
Standard Lot #: 1463724  
Expiration Date: 03/10/2023  
Bottle #: 003  
Last Changed By:  
MALLOY, MICHAEL  
Permit #: 30178

Test	g/210L	Time
Air Blank	0.000	17:44:57
Diagnostic Test	PASS	17:45:33
Air Blank	0.000	17:46:10
Calibration Chk	0.099	17:46:31
Air Blank	0.000	17:47:11
Subject Test 1	DEF*	17:50:39
Air Blank	0.000	17:51:24
Air Blank	0.000	17:52:05
Subject Test 2	0.000	17:52:43
Air Blank	0.000	17:53:23
Wait		17:57:27
Air Blank	0.000	17:58:05
Subject Test 3	INV**	17:58:59
Air Blank	RF1***	17:59:10

\*Deficient Sample  
\*\*Invalid Sample - Begin new deprivation period  
\*\*\*RF1 Detect

Not a Successfully Completed Test Sequence

RESULTS

EXCEPTION MESSAGES

\* Deficient Sample  
\*\* Invalid Sample - Begin new deprivation period  
\*\*\* RF1 Detect  
All air blank results must be 0.000.  
Consecutive subject test results must not differ  
by more than 0.020 g/210L.  
Standard check results must be  $\pm 10\%$ .