



POLICE DEPARTMENT
LAKE HAVASU CITY
2360 McCULLOCH BOULEVARD NORTH
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

Michael Maloy Jr #281
Signature

STATE OF ARIZONA)
) ss
COUNTY OF MOHAVE)

Subscribed and sworn to before me this 30 day of June.

2022 by Michael Maloy

Carla Duarte
NOTARY PUBLIC

6-30-22
DATE

Commission expires:



Area Code 928

- | | | |
|--------------------------------|--------------------------------------|--|
| Administration 855-4884 | Fax #'s | Emergency 9-1-1 |
| Business Office 855-1171 | Administration 680-5430 | Non-Emergency Dispatch/ 855-4111 |
| Investigations 855-5775 | Business Office 680-5431 | Havasu Silent Witness 854-TIPS |
| Patrol 855-0515 | Investigations/Patrol 680-5432 | |
- E-mail: police@lhcaz.gov

EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
INTOXILYZER MODEL 9000

PERIODIC MAINTENTANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALOY #281 AGENCY LHCPCD
DATE 06-30-2022 TIME 1520
INTOXILYZER SERIAL # 90-003695

1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

DIAGNOSTIC TESTS

- 1. Clock time check
- 2. Date check

OPERATIONAL TESTS

- 1. Deficient Subject Test (Proper Sample Recognition)
Deficient Sample printed
- 2. Alcohol-free Subject Test (Proper Sample Recognition):
0.000 AC
- 3. Mouth Alcohol Subject Test (Proper Sample Recognition):
Invalid Sample – Begin new deprivation period printed
- 4. Radio Frequency Interference Test (Error Recognition):
RFI Detect printed
- 5. Standard Calibration Check:
0.100 AC
- 6. Air Blanks Completed
- 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES NO

COMMENTS:

SIGNATURE Michael Maloy #281

INSTRUMENT INFORMATION

Analytical Instrument: INTOXILYZER 9000
 Serial Number: 90-003695
 Software Version: 9439.01.00
 Analytical Report Number: 36950630220006
 QAS: MALOY, MICHAEL
 QAS Permit #: 30178
 Agency: LAKE HAVASU PD
 Last 31-Day Check: 05/19/2022
 Last Annual Maintenance: 11/15/2021

SUBJECT INFORMATION

Test Date: 06/30/2022
 Name: 31-Day Check,
 Driver's License #:
 Weight:
 Gender:
 State of Issue:
 Date of Birth:
 Driver's License Expiration:
 Age:
 Deprivation Start Time: 15:00
 15-Minute Deprivation: Yes

OPERATOR INFORMATION

Name: MALOY, MICHAEL
 Agency: LAKE HAVASU PD
 Permit #: 30178

STANDARD INFORMATION

Standard Value: 0.100
 Standard Lot #: 1463724
 Expiration Date: 03/10/2023
 Bottle #: 003
 Last Changed By:
 MALOY, MICHAEL
 Permit #: 30178

Test	g/210L	Time
Air Blank	0.000	15:20:58
Diagnostic Test	PASS	15:21:33
Air Blank	0.000	15:22:10
Calibration Chk	0.100	15:22:32
Air Blank	0.000	15:23:11
Subject Test 1	DEF*	15:27:47
Air Blank	0.000	15:28:30
Air Blank	0.000	15:29:11
Subject Test 2	0.000	15:29:35
Air Blank	0.000	15:30:19
Wait		15:34:23
Air Blank	0.000	15:35:00
Subject Test 3	INV**	15:35:29
Air Blank	RFI***	15:35:40

*Deficient Sample
 **Invalid Sample - Begin new deprivation period
 ***RFI Detect

Not a Successfully Completed Test Sequence

RESULTSEXCEPTION MESSAGES

* Deficient Sample
 ** Invalid Sample - Begin new deprivation period
 *** RFI Detect
 All air blank results must be 0.000.
 Consecutive subject test results must not differ
 by more than 0.020 g/210L.
 Standard check results must be $\pm 10\%$.