



POLICE DEPARTMENT
LAKE HAVASU CITY
2360 McCULLOCH BOULEVARD NORTH
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

Michael Maloy Jr #231
Signature

STATE OF ARIZONA)
) ss
COUNTY OF MOHAVE)

Subscribed and sworn to before me this 23rd day of March.

2023 by Michael Maloy Jr

[Signature]
NOTARY PUBLIC

2-26-27
DATE



Commission expires:

Area Code 928		
Administration 855-4884	Fax #'s	Emergency 9-1-1
Business Office 855-1171	Administration 680-5430	Non-Emergency Dispatch/ 855-4111
Investigations 855-5775	Business Office 680-5431	Havasu Silent Witness 854-TIPS
Patrol 855-0515	Investigations/Patrol 680-5432	
E-mail: police@lhcaz.gov		

281

EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALBY #281 AGENCY LHCPD
DATE 03-23-2023 TIME 15:13
INTOXILYZER SERIAL # 90-003680

☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

DIAGNOSTIC TESTS

- ☒ 1. Clock time check
☒ 2. Date check

OPERATIONAL TESTS

☒ 1. Deficient Subject Test (Proper Sample Recognition)

Deficient Sample printed

☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):
0.000 AC

☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):

Invalid Sample – Begin new deprivation period printed

☒ 4. Radio Frequency Interference Test (Error Recognition):

RFI Detect printed

☒ 5. Standard Calibration Check:
0.100 AC

☒ 6. Air Blanks Completed

☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

SIGN 8

SIGNATURE

Michael Malby #281

DPS Form Exh I-2 (Rev 19-03)

INSTRUMENT INFORMATION
Analytical Instrument: INTOXILYZER 9000
Serial Number: 90-003680
Software Version: 9439.01.00
Analytical Report Number: 3680032230025
QRS: MALLOY, MICHAEL
QRS Permit #: 30178
Agency: LAKE HAVASU PD
Last 31-Day Check: 12/07/2022
Last Annual Maintenance: 11/29/2022

SUBJECT INFORMATION
Test Date: 03/23/2023
Name: 31-Day Check,
Driver's License #:
Weight:
Gender:
State of Issue:
Date of Birth:
Driver's License Expiration:
Age:
Deprivation Start Time: 14:55
15-Minute Deprivation: Yes

OPERATOR INFORMATION
Name: MALLOY, MICHAEL
Agency: LAKE HAVASU PD
Permit #: 30178

STANDARD INFORMATION
Standard Value: 0.100
Standard Lot #: 302-402376471
Expiration Date: 06/02/2024
Bottle #: 053
Last Changed By:
MALLOY, MICHAEL
Permit #: 30178

Test	g/210L	Time
Air Blank	0.000	15:13:43
Diagnostic Test	PASS	15:14:19
Air Blank	0.000	15:14:56
Calibration Chk	0.100	15:15:18
Air Blank	0.000	15:15:57
Subject Test 1	DEF*	15:19:11
Air Blank	0.000	15:19:54
Air Blank	0.000	15:20:34
Subject Test 2	0.000	15:21:01
Air Blank	0.000	15:21:43
Wait		15:25:46
Air Blank	0.000	15:26:23
Subject Test 3	INV**	15:26:56
Air Blank	RFI***	15:27:08

xDeficient Sample
**Invalid Sample - Begin new deprivation period
***RFI Detect

Not a Successfully Completed Test Sequence

RESULTS

EXCEPTION MESSAGES

* Deficient Sample
** Invalid Sample - Begin new deprivation period
*** RFI Detect
All air blank results must be 0.000.
Consecutive subject test results must not differ
by more than 0.020 g/210L.
Standard check results must be ±10%.