



POLICE DEPARTMENT

**LAKE HAVASU CITY**

2360 McCULLOCH BOULEVARD NORTH  
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

Michael Maloy #281  
Signature

STATE OF ARIZONA           )  
  ) ss  
COUNTY OF MOHAVE       )

Subscribed and sworn to before me this 19 day of MAY.

2025 by MICHAEL MALOY


[Signature]

NOTARY PUBLIC

5-19-2025

DATE

Commission expires: 3-16-2029



Area Code 928

Administration ..... 855-4884  
Business Office ..... 855-1171  
Investigations ..... 855-5775  
Patrol ..... 855-0515

Fax #'s  
Administration ..... 680-5430  
Business Office ..... 680-5431  
Investigations/Patrol ..... 680-5432

Emergency ..... 9-1-1  
Non-Emergency Dispatch/ ..... 855-4111  
Havasut Silent Witness ..... 854-TIPS

E-mail: police@lhcaz.gov

281

## EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY  
INTOXILYZER MODEL 9000

## PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALDY #281 AGENCY LNC PD  
DATE 05-19-2025 TIME 22:00  
INTOXILYZER SERIAL # 90-003695

- ☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

## DIAGNOSTIC TESTS

- ☒ 1. Clock time check  
☒ 2. Date check

## OPERATIONAL TESTS

- ☒ 1. Deficient Subject Test (Proper Sample Recognition)  
Deficient Sample printed
- ☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):  
0.000 AC
- ☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):  
Invalid Sample – Begin new deprivation period printed
- ☒ 4. Radio Frequency Interference Test (Error Recognition):  
RFI Detect printed
- ☒ 5. Standard Calibration Check:  
0.099 AC
- ☒ 6. Air Blanks Completed
- ☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

P.S.I. 225

SIGNATURE



## ARIZONA FORENSIC BREATH ALCOHOL ANALYTICAL REPORT

INSTRUMENT INFORMATION

Analytical Instrument: Intoxilyzer 9000  
 Serial Number: 90-003695  
 Software Version: 9439.01.00  
 Analytical Report Number: 36950519250295

QAS: MALOY, MICHAEL  
 QAS Permit #: 30178  
 Agency: LAKE HAVASU PD  
 Last 31-Day Check: 04/28/2025  
 Last Annual Maintenance: 10/28/2024

SUBJECT INFORMATION

Name: 31-Day Check  
 Test Date: 05/19/2025  
 Driver's License #:  
 Gender:  
 Date of Birth:  
 Age:

Weight:  
 State of Issue:  
 Driver's License Expiration:  
 Deprivation Start Time: 21:30  
 15 - Minute Deprivation: Yes

OPERATOR INFORMATION

Name: MALOY, MICHAEL  
 Agency: LAKE HAVASU PD

Permit #: 30178  
STANDARD INFORMATION  
 Standard Value: 0.100  
 Standard Lot #: 302-402972207  
 Expiration Date: 02/20/2026  
 Bottle #: 022  
 Last Changed By: MALOY, MICHAEL

Test	g/210L	Time
Air Blank	0.000	22:00:10
Diagnostic Test	PASS	22:00:45
Air Blank	0.000	22:01:23
Calibration Chk	0.099	22:01:44
Air Blank	0.000	22:02:24
Subject Test 1	DEF*	22:05:39
Air Blank	0.000	22:06:22
Air Blank	0.000	22:07:02
Subject Test 2	0.000	22:07:31
Air Blank	0.000	22:08:11
Wait		22:12:16
Air Blank	0.000	22:12:53
Subject Test 3	INV**	22:14:44
Air Blank	RFI***	22:14:59

Permit #: 30178

RESULTSEXCEPTION MESSAGES

\*Deficient Sample  
 \*\*Invalid Sample - Begin new deprivation period  
 \*\*\*RFI Detect

\* Deficient Sample  
 \*\* Invalid Sample - Begin new deprivation period  
 \*\*\* RFI Detect

OPERATOR COMMENTS

Not a Successfully Completed Test Sequence

All air blank results must be 0.000.  
 Consecutive subject test results must not differ by more than 0.020 g/210L.  
 Standard check results must be  $\pm 10\%$ .