



POLICE DEPARTMENT

LAKE HAVASU CITY

2360 McCULLOCH BOULEVARD NORTH
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

Michael Maloy Jr #281
Signature

STATE OF ARIZONA)
) ss
COUNTY OF MOHAVE)


Subscribed and sworn to before me this 24th day of May.

2023 by Michael Maloy

Shawna McKnight
NOTARY PUBLIC

May 24, 2023
DATE

Commission expires: May 4, 2025



Area Code 928

Administration 855-4884
Business Office 855-1171
Investigations 855-5775
Patrol 855-0515

Fax #'s
Administration 680-5430
Business Office 680-5431
Investigations/Patrol 680-5432

Emergency 9-1-1
Non-Emergency Dispatch/ 855-4111
Havasus Silent Witness 854-TIPS

E-mail: police@lhcaz.gov

281

EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALOY #281 AGENCY LHCPD
DATE 05-24-2023 TIME 07:27
INTOXILYZER SERIAL # 90-003695

☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

DIAGNOSTIC TESTS

- ☒ 1. Clock time check
☒ 2. Date check

OPERATIONAL TESTS

- ☒ 1. Deficient Subject Test (Proper Sample Recognition)

Deficient Sample printed

- ☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):
0.000 AC

- ☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):

Invalid Sample – Begin new deprivation period printed

- ☒ 4. Radio Frequency Interference Test (Error Recognition):
RFI Detect printed

- ☒ 5. Standard Calibration Check:
0.102 AC

- ☒ 6. Air Blanks Completed
☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

SIGNATURE

Michael Maloy Jr #281

ARIZONA FORENSIC BREATH ALCOHOL ANALYTICAL REPORT

INSTRUMENT INFORMATION

Analytical Instrument: Intoxilyzer 9000
 Serial Number: 90-003695
 Software Version: 9439.01.00
 Analytical Report Number: 36950524230130

QAS: MALOY, MICHAEL
 QAS Permit #: 30178
 Agency: LAKE HAVASU PD
 Last 31-Day Check: 04/26/2023
 Last Annual Maintenance: 11/28/2022

SUBJECT INFORMATION

Name: 31-Day Check
 Test Date: 05/24/2023
 Driver's License #:
 Gender:
 Date of Birth:
 Age:

Weight:
 State of Issue:
 Driver's License Expiration:
 Deprivation Start Time: 07:00
 15 - Minute Deprivation: Yes

OPERATOR INFORMATION

Name: MALOY, MICHAEL
 Agency: LAKE HAVASU PD

Permit #: 30178
STANDARD INFORMATION
 Standard Value: 0.100
 Standard Lot #: 302-402454776
 Expiration Date: 06/16/2024
 Bottle #: 001
 Last Changed By: MALOY, MICHAEL

Test	g/210L	Time
Air Blank	0.000	07:27:43
Diagnostic Test	PASS	07:28:19
Air Blank	0.000	07:28:56
Calibration Chk	0.102	07:29:17
Air Blank	0.000	07:29:58
Subject Test 1	DEF*	07:33:10
Air Blank	0.000	07:33:55
Air Blank	0.000	07:34:36
Subject Test 2	0.000	07:35:02
Air Blank	0.000	07:35:43
Wait		07:39:48
Air Blank	0.000	07:40:25
Subject Test 3	INV**	07:41:08
Air Blank	RFI***	07:41:25

*Deficient Sample
 **Invalid Sample - Begin new deprivation period
 ***RFI Detect

Permit #: 30178

RESULTSEXCEPTION MESSAGES

* Deficient Sample
 ** Invalid Sample - Begin new deprivation period
 *** RFI Detect

OPERATOR COMMENTS

Not a Successfully Completed Test Sequence

*All air blank results must be 0.000.
 Consecutive subject test results must not differ by more than 0.020 g/210L.
 Standard check results must be $\pm 10\%$.*