



POLICE DEPARTMENT
LAKE HAVASU CITY
2360 McCULLOCH BOULEVARD NORTH
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

Michael Maloy Jr #281
Signature

STATE OF ARIZONA)
COUNTY OF MOHAVE) ss)

Subscribed and sworn to before me this 24 day of NOVEMBER

2025 by MICHAEL MALOY
Jennifer Lentz
NOTARY PUBLIC

11/24/2025
DATE



Commission expires: 03/15/2029

Area Code 928

Administration 855-4884
Business Office 855-1171
Investigations 855-5775
Patrol 855-0515

Fax #'s
Administration 680-5430
Business Office 680-5431
Investigations/Patrol 680-5432

E-mail: police@lhcaz.gov

Emergency 9-1-1
Non-Emergency Dispatch/ 855-4111
Havasu Silent Witness 854-TIPS

281

EXHIBIT I-2
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALOY #281 AGENCY LHCPD
DATE 11-24-2025 TIME 22:55
INTOXILYZER SERIAL # 90-003680

- ☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

DIAGNOSTIC TESTS

- ☒ 1. Clock time check
☒ 2. Date check

OPERATIONAL TESTS

- ☒ 1. Deficient Subject Test (Proper Sample Recognition)
Deficient Sample printed
☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):
0. 000 AC
☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):
Invalid Sample – Begin new deprivation period printed
☒ 4. Radio Frequency Interference Test (Error Recognition):

RFI Detect printed

- ☒ 5. Standard Calibration Check:
0. 097 AC
☒ 6. Air Blanks Completed
☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

P.S.I.: 825

SIGNATURE Michael Maloy #281

ARIZONA FORENSIC BREATH ALCOHOL
ANALYTICAL REPORT

INSTRUMENT INFORMATION

Analytical Instrument: INTOXILYZER 9000
Serial Number: 90-003680
Software Version: 9439.01.00
Analytical Report Number: 36801124250058
OAS: MALOY, MICHAEL
OAS Permit #: 30178
Agency: LAKE HAVASU PD
Last 31-Day Check: 10/08/2025
Last Annual Maintenance: 10/21/2025

SUBJECT INFORMATION

Test Date: 11/24/2025
Name: 31-Day Check,
Driver's License #:
Weight:
Gender:
State of Issue:
Date of Birth:
Driver's License Expiration:
Age:
Deprivation Start Time: 22:30
15-Minute Deprivation: Yes

OPERATOR INFORMATION

Name: MALOY, MICHAEL
Agency: LAKE HAVASU PD
Permit #: 30178

STANDARD INFORMATION

Standard Value: 0.100
Standard Lot #: 302-402972207
Expiration Date: 02/20/2026
Bottle #: 024
Last Changed By:
MALOY, MICHAEL
Permit #: 30178

Test	g/210L	Time
Air Blank	0.000	22:55:52
Diagnostic Test	PASS	22:56:28
Air Blank	0.000	22:57:05
Calibration Chk	0.097	22:57:27
Air Blank	0.000	22:58:06
Subject Test 1	DEF*	23:01:26
Air Blank	0.000	23:02:56
Air Blank	0.000	23:03:37
Subject Test 2	0.000	23:04:17
Air Blank	0.000	23:04:59
Wait		23:09:02
Air Blank	0.000	23:09:39
Subject Test 3	INV**	23:10:13
Air Blank	RF1***	23:10:26

xDeficient Sample

**Invalid Sample - Begin new deprivation period

***RF1 Detect

Not a Successfully Completed Test Sequence

RESULTS

EXCEPTION MESSAGES

x Deficient Sample

** Invalid Sample - Begin new deprivation period

*** RF1 Detect

All air blank results must be 0.000.

Consecutive subject test results must not differ
by more than 0.020 g/210L.

Standard check results must be ±10%.