



POLICE DEPARTMENT

**LAKE HAVASU CITY**

2360 McCULLOCH BOULEVARD NORTH  
LAKE HAVASU CITY, ARIZONA 86403-5947

To Whom It May Concern:

I hereby attest that Michael T. Maloy, Jr. is a Certified Intoxilyzer Quality Assurance Specialist for the Lake Havasu City Police Department.

I certify that the attached documentation of Standard Quality Assurance Procedures and/or Standard Calibration Check Procedure are full, true and correct copy of the original.

*Michael Maloy Jr #281*  
\_\_\_\_\_  
Signature

STATE OF ARIZONA            )  
                                          ) ss  
COUNTY OF MOHAVE        )

Subscribed and sworn to before me this 26 day of SEPTEMBER.


2024 by MICHAEL MALOY

\_\_\_\_\_  
NOTARY PUBLIC

9-26-2024

DATE

Commission expires: 3-16-2025



Area Code 928

Administration ..... 855-4884  
Business Office ..... 855-1171  
Investigations ..... 855-5775  
Patrol ..... 855-0515

Fax #'s  
Administration ..... 680-5430  
Business Office ..... 680-5431  
Investigations/Patrol ..... 680-5432

Emergency ..... 9-1-1  
Non-Emergency Dispatch/ ..... 855-4111  
Havasus Silent Witness ..... 854-TIPS

E-mail: [police@lhcaz.gov](mailto:police@lhcaz.gov)

281

## EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY  
INTOXILYZER MODEL 9000

## PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST M. MALOY #281 AGENCY LHCPD  
DATE 09-26-2024 TIME 0354  
INTOXILYZER SERIAL # 90-603696

- ☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration 0.100 AC

## DIAGNOSTIC TESTS

- ☒ 1. Clock time check  
☒ 2. Date check

## OPERATIONAL TESTS

- ☒ 1. Deficient Subject Test (Proper Sample Recognition)  
Deficient Sample printed
- ☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):  
0. 000 AC
- ☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):  
Invalid Sample – Begin new deprivation period printed
- ☒ 4. Radio Frequency Interference Test (Error Recognition):  
RFI Detect printed
- ☒ 5. Standard Calibration Check:  
0. 099 AC
- ☒ 6. Air Blanks Completed
- ☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

STANDARD CHANGEP.S.I. 975

SIGNATURE

Michael Maloy Jr #281

## ARIZONA FORENSIC BREATH ALCOHOL ANALYTICAL REPORT

INSTRUMENT INFORMATION

Analytical Instrument: Intoxilyzer 9000  
 Serial Number: 90-003696  
 Software Version: 9439.01.00  
 Analytical Report Number: 36960926240048

QAS: MALOY, MICHAEL  
 QAS Permit #: 30178  
 Agency: LAKE HAVASU PD  
 Last 31-Day Check: 08/26/2024  
 Last Annual Maintenance: 01/10/2024

SUBJECT INFORMATION

Name: 31-Day Check  
 Test Date: 09/26/2024  
 Driver's License #:  
 Gender:  
 Date of Birth:  
 Age:

Weight:  
 State of Issue:  
 Driver's License Expiration:  
 Deprivation Start Time: 03:30  
 15 - Minute Deprivation: Yes

OPERATOR INFORMATION

Name: MALOY, MICHAEL  
 Agency: LAKE HAVASU PD

Permit #: 30178

STANDARD INFORMATION

Standard Value: 0.100  
 Standard Lot #: 302-402972207  
 Expiration Date: 02/20/2026  
 Bottle #: 023  
 Last Changed By: MALOY, MICHAEL

Permit #: 30178

| Test            | g/210L | Time     |
|-----------------|--------|----------|
| Air Blank       | 0.000  | 03:54:48 |
| Diagnostic Test | PASS   | 03:55:24 |
| Air Blank       | 0.000  | 03:56:01 |
| Calibration Chk | 0.099  | 03:56:22 |
| Air Blank       | 0.000  | 03:57:02 |
| Subject Test 1  | DEF*   | 04:00:14 |
| Air Blank       | 0.000  | 04:01:00 |
| Air Blank       | 0.000  | 04:01:40 |
| Subject Test 2  | 0.000  | 04:02:05 |
| Air Blank       | 0.000  | 04:02:47 |
| Wait            |        | 04:06:51 |
| Air Blank       | 0.000  | 04:07:28 |
| Subject Test 3  | INV**  | 04:07:56 |
| Air Blank       | RFI*** | 04:08:10 |

\*Deficient Sample  
 \*\*Invalid Sample - Begin new deprivation period  
 \*\*\*RFI Detect

RESULTSEXCEPTION MESSAGES

\* Deficient Sample  
 \*\* Invalid Sample - Begin new deprivation period  
 \*\*\* RFI Detect

OPERATOR COMMENTS

Not a Successfully Completed Test Sequence

All air blank results must be 0.000.  
 Consecutive subject test results must not differ by more than 0.020 g/210L.  
 Standard check results must be  $\pm 10\%$ .

STANDARD CHANGE

281

Intoxilyzer - Alcohol Analyzer

Model 9000

SN: 90-003696

Test Date: 09/26/2024

Test Time: 03:52

Location:

Software Version: 9439.01.00

Standard Lot #: 302-402972207

Standard Value: 0.100

Expiration Date: 02/20/2026

Bottle #: 023

Last Changed By: MALOY, MICHAEL

Permit #: 30178

Operator: MALOY, MICHAEL

Permit #: 30178

Agency: LAKE HAVASU PD

| Test            | g/210L | Time     |
|-----------------|--------|----------|
| Air Blank       | 0.000  | 03:52:23 |
| Calibration Chk | 0.099  | 03:52:45 |
| Air Blank       | 0.000  | 03:53:25 |

No RFI Detected

Successfully Completed Test Sequence